Beyond the OOT Result: Could Previous Measurements Have Been Affected?



simco

Contents

Executive summary 3

Introduction: An OOT result is a starting point, not a conclusion 4

Part 1: What does an OOT calibration result establish? 5

Part 2: As-found and as-left results answer different questions 6

Part 3: Identify exactly what was outside tolerance 8

Part 4: Was the affected measurement capability actually used? 9

Part 5: Compare the calibration result with the actual application 10

Part 6: Consider magnitude, direction, and measurement uncertainty 11

Part 7: What other evidence may help clarify the result? 13

Part 8: Questions to ask the calibration provider 15

Part 9: Know where calibration interpretation ends 17

Part 10: Organize the information for further evaluation 18

Conclusion: Look beyond the OOT label 21

Resources:

OOT Calibration Result Review Guide 22

OOT Information and Evidence Worksheet 24

Executive summary

An out-of-tolerance (OOT) result tells you what was found during calibration. The harder question is what that finding could mean for measurements and decisions made before calibration.

The OOT designation alone does not establish that previous measurements were inaccurate or affected. Understanding its potential relevance may require looking at the specific measurement capability involved, magnitude and direction of error, actual instrument use, application requirements, measurement uncertainty, and available historical evidence.

This guide explains how to interpret that technical information, what questions may help qualified teams evaluate previous use and where calibration interpretation ends, and customer quality-system decisions begin.

Key takeaways

Readers will learn:

- Why an OOT result does not automatically mean an instrument was unfit for its actual application
- What as-found and as-left results each establish
- How to identify the affected measurement capability and why the magnitude and direction of error matter
- How actual instrument use may help narrow which previous measurements are relevant
- Why calibration specifications may differ from the requirements of the actual application
- What calibration, usage, application, and historical evidence may help clarify previous performance
- What questions to ask a calibration provider and where calibration interpretation ends and customer quality-system decisions begin



Introduction: An OOT result is a starting point, not a conclusion


Why OOT results create concern

An OOT notification can raise immediate questions about previous use. Was the instrument producing inaccurate measurements? When might the condition have begun? Which previous measurements could be relevant? Could an acceptance or maintenance decision have changed? Does the reported condition apply to every way the instrument was used?

Those concerns lead to the central question: Could the reported OOT condition have affected previous measurement results or decisions?

The OOT designation alone does not provide enough information to answer it. An instrument may have multiple functions, ranges and test points, and the reported condition may involve only one of them. Understanding its potential relevance may require considering the affected measurement capability, how the instrument was used, what the application required and what other evidence is available about previous performance.

Understanding the reported calibration condition and the evidence surrounding it provides a more useful starting point than drawing conclusions from the OOT designation alone. The calibration provider can help explain the technical evidence associated with the instrument, while the customer's qualified functions determine what that information may mean for its applications, products, processes, and other decisions under its approved procedures and applicable requirements.



Part 1: What does an OOT calibration result establish?

How an OOT result is determined


A calibration compares an instrument's measured performance with defined requirements. An OOT result generally indicates that one or more as-found results did not meet the applicable calibration tolerance, specification or acceptance criterion, considering the applicable decision rule when a conformity statement is provided.

Understanding the result therefore begins with identifying the requirement that was exceeded. Depending on the calibration service, that requirement could be a manufacturer specification, a customer-specified calibration tolerance or another documented calibration requirement. When a conformity statement is requested, the applicable decision rule defines how measurement uncertainty is considered in determining conformity and is agreed with the customer unless it is inherent in the requested specification or standard.

That distinction is important because the requirement used to determine calibration conformity may differ from the performance required for the instrument's actual application. An instrument could exceed a particular calibration specification without necessarily being unsuitable for every application in which it was used. Determining whether the observed condition was relevant to a specific application requires information beyond the OOT designation itself.

Terminology can create additional confusion. Terms such as out of tolerance, out of calibration, failed calibration, outside manufacturer specification and unfit for intended purpose should not automatically be treated as interchangeable. Each may refer to a different requirement, condition or conclusion.

The calibration data provide a more useful starting point: What requirement was applied, which result did not meet it, and what was observed during calibration? Whether that condition could have affected previous use requires additional context.



Part 2: As-found and as-left results answer different questions

When an instrument is adjusted or repaired during calibration service, its condition before and after that work provides different information. Understanding that distinction is particularly important when considering an OOT result.

What do as-found data tell you?

As-found data document the instrument's observed condition before adjustment or repair. Depending on the calibration service and available data, they may identify the affected function, range and test point, the applicable tolerance or specification, the measured result, measurement uncertainty and whether other tested points passed or failed.

For an OOT result, these data may also show the magnitude and direction of the observed deviation. That information can help define the specific calibration condition that may warrant further consideration.

As-found data have limits, however. They document the condition observed during calibration. They may not establish when that condition began, whether the instrument performed consistently throughout the previous calibration interval, or whether the observed error existed during a particular previous measurement.



What do as-left data tell you?

As-left data document the instrument's condition after any required adjustment or repair. An acceptable as-left result demonstrates that the instrument has been returned to an acceptable condition for continued use, based on the applicable calibration requirements.

However, correcting the instrument does not by itself resolve the potential impact of an out-of-tolerance as-found condition on prior measurements. The as-found data may still need to be evaluated to determine when the condition may have developed and whether measurements made since the previous calibration could have been affected.

As-found vs. as-left

As-found condition	As-left condition
Before adjustment or repair	After adjustment or repair
Relevant to understanding prior performance	Relevant to current condition
May support review of previous use	Does not resolve previous-use questions by itself



Part 3: Identify exactly what was outside tolerance

An OOT designation can summarize a much more specific finding. An instrument may support multiple functions and measurement ranges, with calibration performed at multiple test points. One capability may be outside its applicable requirement while others meet theirs.

That makes the details behind the designation important. Start with the instrument and asset identification, calibration date, and requirement used to determine conformity. The calibration data may then show which function, range and test point or points were affected, along with the reported as-found result and applicable tolerance or acceptance limit.

Other information can further define the observed condition. Depending on the calibration data available, this may include:

- Magnitude and direction of the deviation
- Measurement uncertainty
- The applicable decision rule
- Whether the result was repeated or confirmed
- Whether related functions, ranges and test points met their applicable requirements

Together, these details can help answer more focused technical questions. What exactly was outside tolerance? How far outside the applicable requirement was the result? Did the observed error bias the measurement high or low? Was the condition consistent or intermittent? Were related capabilities affected?

Complete as-found data can be particularly useful when available because they provide more information than the OOT designation alone. However, the observed deviation should not automatically be treated as an exact correction that can be applied retrospectively to previous measurements. The as-found result may not establish when the condition began or whether the error remained constant before calibration.

Part 4: Was the affected measurement capability actually used?


Once the affected capability has been identified, actual instrument use can help narrow which previous measurements may be relevant. If the OOT condition involved a function, range or test point that was not used, that information may substantially change the scope of further consideration.

Usage records can help connect the calibration finding with previous work. Depending on the instrument and the organization's recordkeeping, useful questions may include:

- Which functions and measurement ranges were used?
- Were measurements made near the affected test point?
- Where and during what period was the instrument used?
- What was measured?
- What decisions depended on those measurements?
- Was the instrument used for indication or for formal acceptance?
- Were redundant or confirming measurements available?

Potential sources include instrument-use records, work orders, production and test records, maintenance or field-service records, batch, lot or serial-number records, instrument-location history, software audit trails and operator or technician records.

Usage records may not provide complete traceability to every previous measurement. The previous calibration interval may provide a timeframe for consideration, but it should not automatically be treated as a period in which all work was affected. Actual usage and other available evidence may help qualified teams narrow which previous measurements warrant further consideration.



Part 5: Compare the calibration result with the actual application

Once relevant uses have been identified, the next question is what level of measurement performance those applications require.

As discussed earlier, the requirement used to determine calibration conformity may differ from the requirement governing the actual application. The calibration provider evaluates the instrument against the identified calibration requirement. The customer's qualified functions understand the tolerances, acceptance criteria, and measurement needs associated with the work the instrument supported.

That comparison may involve more than a single tolerance value. Depending on the application, relevant information could include:

- Product or process tolerances
- Maintenance or service limits
- Acceptance criteria
- Required measurement capability
- Instrument configuration and measurement range
- Environmental conditions
- Fixtures, probes, cables or software used with the instrument
- Applicable guard bands or decision rules

Previous measurement results may also provide important context. A result close to the customer's applicable measurement-process acceptance limit may present different technical considerations from one well within that limit. The calibration acceptance limit provides context for the OOT finding, while the customer's measurement-process acceptance limit helps qualified teams consider whether the observed error could have been significant to the previous work.

Useful questions may include: What measurement requirement applied to the work? Were previous results close enough to the customer's applicable measurement-process acceptance limit for the observed condition to potentially matter? Could the direction of the error have changed the interpretation of a result? Is independent evidence available that may help confirm or challenge the original measurement?

Part 6: Consider magnitude, direction, and measurement uncertainty

The size and direction of an observed deviation provide additional context for interpreting an OOT result. A result slightly beyond an applicable calibration requirement presents a different technical question from a substantially larger deviation, although the size of the deviation alone does not establish the significance of the finding for a particular application.

How does the direction of error matter?

Direction helps show how the observed condition could influence a measurement. A positive or negative bias may indicate that measured values appeared higher or lower than they otherwise would have.

When previous measurements were used against an acceptance limit, this information may help qualified teams consider whether the direction of the observed error could have changed the interpretation of a result. Its relevance depends on the application, the measurement values involved and the applicable acceptance criteria.



How does measurement uncertainty affect interpretation?

Calibration results have associated measurement uncertainty, which characterizes the possible variation associated with the measurement result. This uncertainty may be particularly relevant when interpreting results near a specification or acceptance limit.

A conformity statement may also depend on the decision rule used to account for measurement uncertainty. A decision rule defines how measurement uncertainty is accounted for when determining whether a result conforms to a specified requirement. Guard bands may be used as part of that approach by establishing an acceptance limit inside the specification limit to account for uncertainty.

For these reasons, the reported deviation should not necessarily be treated as an exact correction that can be applied in isolation to previous measurements. The measured result, associated uncertainty, applicable requirement and decision rule may all provide relevant context for interpreting the calibration finding.

The measurement uncertainty reported with the calibration result applies to the calibration measurement itself. It should not be assumed to represent the uncertainty associated with the customer's previous measurement process, which may include additional contributions from the instrument, method, environment, fixtures, probes, cables, operator and other factors.



Part 7: What other evidence may help clarify the result?

Calibration and usage data may not tell the entire story. Historical records, independent measurements and documented events can provide additional evidence about how an instrument may have performed before the OOT condition was identified.

What can calibration history show?

Previous calibration records may reveal patterns that are not apparent from a single result. Useful information could include previous as-found results, the direction and rate of observed drift, repeated adjustments, earlier OOT conditions, repair history and intermediate verification results.

Known performance or drift characteristics, common failure modes or similar findings among comparable instruments may help identify patterns or areas for further evaluation. However, this information does not establish the historical performance of the specific instrument being evaluated.

What independent evidence may be available?


Other measurement or process records may help provide additional context for previous results. Examples include:

- Measurements from a second instrument
- Redundant measurements
- In-process checks
- Reference standard results
- Product or process monitoring
- Retest data
- Environmental monitoring
- System-generated records

The relevance of this evidence depends on what was measured, how the information was generated, and whether it relates to the affected measurement capability and period under consideration.

Were there known events that could provide additional context?
Instrument history may also identify events or conditions that could be relevant to understanding the calibration finding. Records may show damage, overload, transportation incidents, unusual environmental exposure, storage problems, changes in instrument behavior or maintenance and repair activity.

Taken together, these sources can help build a more complete technical picture. However, historical evidence has limits. A current as-found result may not establish when a condition began, whether drift occurred at a constant rate, whether performance remained stable between calibrations or whether the same error existed during every previous use.



Part 8: Questions to ask the calibration provider

When an OOT result raises questions, the calibration provider may be able to supply additional technical detail or clarify the information already reported. The specific information available will depend on the calibration performed, service level and applicable documentation.

Useful questions may include:

- Can you provide complete as-found and as-left data?
- Which functions, ranges and test points were outside tolerance?
- What calibration requirement or specification was exceeded?
- What was the magnitude and direction of the observed deviation?
- What measurement uncertainty applies to the reported result?
- What decision rule was used?
- Was the OOT result repeated or otherwise confirmed?
- Were any unusual conditions observed during calibration?
- Was the instrument adjusted or repaired?
- Are previous calibration or repair results available?
- Is technical consultation available to help interpret the calibration data?



What should customers consider before future service?

OOT events can also highlight opportunities to clarify service expectations before the next calibration. Depending on the organization, instrument and service agreement, customers may want to discuss:

- Who should receive OOT notifications
- Preferred notification timing
- Desired as-found data
- Authorization before adjustment or repair, including whether the instrument should be returned in its as-found condition to support further evaluation
- Certificate and calibration-data detail
- Access to historical calibration and repair records
- Technical points of contact for questions about results

Preserving the instrument's as-found condition may be important when the customer needs additional evidence, such as repeating previous measurements or comparing the instrument's results with other available evidence. Once the instrument is adjusted or repaired, that opportunity may no longer be available.

Not every calibration service includes the same level of data, notification or technical support. Establishing expectations in advance can help ensure that the information most useful to the customer is available when an OOT condition occurs.



Part 9: Know where calibration interpretation ends

Evaluating an OOT result may bring together information from the calibration provider and the customer, but each has a different role.

What can the calibration provider help explain?
SIMCO can help customers understand the technical evidence associated with the calibration, including:

- What was measured
- What calibration requirement was applied
- Which results were outside tolerance
- The magnitude and direction of the observed deviation
- Measurement uncertainty
- Applicable decision rules
- Available calibration and repair history
- Relevant technician observations

This information can help clarify the instrument's observed calibration condition and provide technical context for further evaluation.

What does the customer determine?
The customer's qualified functions evaluate that evidence in the context of the instrument's actual use, products, processes, procedures and applicable requirements. Depending on the circumstances, those functions determine whether previous product or work was affected and whether additional review, retesting, reinspection, containment, corrective action, communication, documentation or approvals are appropriate.

The distinction is important: the calibration provider supplies and helps interpret technical evidence about the instrument. The customer determines what that evidence means for its previous work and what response, if any, is appropriate under its quality system and applicable requirements.

Part 10: Organize the information for further evaluation

By this point, an OOT result may involve information from several sources. Bringing that information together can make it easier for qualified teams to see what is known, what remains uncertain and what additional technical information may be useful.

Not every category will be relevant to every OOT result. The objective is to organize the available technical evidence, not prescribe a required sequence or conclusion.


Companion Tools for Further Evaluation

Two companion resources follow the conclusion to help you apply the concepts discussed in this eBook:

OOT Calibration Result Review Guide
Use the Guide to identify questions worth considering, including what was outside tolerance, whether the affected capability was used, what the application required and what other evidence may help clarify previous performance.

OOT Information and Evidence Worksheet
Use the Worksheet to capture available information relevant to those questions, including calibration results, instrument use, application requirements, supporting evidence and open questions.

The Guide helps frame the questions; the Worksheet provides a place to organize the evidence. Use either or both as appropriate. Not every question or information category will apply, and neither resource prescribes a required investigation process or conclusion.



How might the evidence change the technical picture?

The following simplified examples illustrate how the questions in the Guide and the information organized in the Worksheet can help clarify an OOT finding. Each shows how connecting calibration findings with actual use, application requirements, or other evidence can bring the technical picture into better focus. These examples demonstrate technical considerations rather than prescribe a particular response.

Example 1: The affected function was not used

A multifunction instrument is found OOT on one measurement function. Usage records indicate that the instrument was used during the previous calibration interval, but the affected function was not used for the work under consideration.

Identifying the specific affected capability and comparing it with actual instrument use substantially narrows the technical question. The OOT designation alone would not have provided that distinction.

Example 2: Calibration and application requirements differed


An instrument is found outside the calibration specification applied during service. Records show that the actual application used a different measurement requirement.

The OOT finding remains relevant calibration information, but determining its potential significance requires comparing the observed deviation with the requirement that applied to the actual work. Being outside one calibration specification does not, by itself, establish that the instrument was unsuitable for that application.

Example 3: Previous results were near an acceptance limit

An instrument is found OOT on a measurement capability that records show was used for previous acceptance measurements. Some of those results were close to the applicable acceptance limit.

In this situation, the magnitude and direction of the observed deviation, measurement uncertainty, actual instrument use and available confirming evidence may provide important additional context. The calibration finding alone does not establish whether previous acceptance decisions were affected, but the available technical information can help the customer's qualified functions evaluate the question more fully.



Conclusion: Look beyond the OOT label

An OOT result is important technical information, but the designation alone does not answer the question that often matters most: Could previous measurements, products or decisions have been affected?

Answering that question may require a more complete view of the calibration result, how the instrument was used, what the application required and what other evidence is available. The ability to connect an instrument to the work it supported can make that evaluation significantly more focused.

For organizations with strong equipment-to-product traceability, this evaluation can become much more focused. When organizations can link measurement equipment to specific products, lots, batches, inspections or other quality activities, they are better positioned to identify which work may warrant further review rather than treating every use during the previous calibration interval as equally relevant. CERDAAC Product Traceability Cloud is designed to help establish that connection between manufacturing equipment and the products produced, supporting faster identification of products potentially affected by a non-conformance.

The calibration provider plays an important role in making the technical evidence available and helping customers understand what the calibration results show. Better as-found data, accessible calibration history, clear communication, instrument-use visibility and product traceability can give qualified customer teams stronger information for evaluating an OOT finding in the context of their own applications and requirements.

Do you have the calibration data and technical support needed when an instrument is found out of tolerance? Talk with SIMCO about as-found data, calibration history, technical consultation and program visibility.

Watch SIMCO's OOT Video Series

OOT Calibration Result Review Guide

When an instrument is found out of tolerance (OOT), the calibration result may raise questions about previous measurements or decisions. The questions below can help organize the technical information that may be relevant to further evaluation.

What was outside tolerance?

- What instrument and asset ID are associated with the result?
- Which function, range and test point or points were affected?
- What calibration requirement, tolerance or specification was exceeded?
- What was the reported as-found result?
- Did other tested functions, ranges or test points meet their applicable requirements?

How large was the observed deviation?

- How far was the as-found result from the applicable requirement?
- Was the result repeated or otherwise confirmed?
- Is measurement uncertainty reported for the result?

In which direction was the deviation?

- Was the observed deviation positive or negative?
- Could the direction of the error be relevant to how previous measurements would have been interpreted?

Was the affected measurement capability actually used?

- Was the affected function or range used during the period under consideration?
- Were previous measurements made at or near the affected test point?
- What work did the instrument support?
- What usage records are available?

What did the application require?

- What measurement requirement applied to the previous work?
- What product, process, maintenance or other acceptance criteria applied?
- Were relevant previous results close to an acceptance limit?
- Were any applicable decision rules or guard bands involved?

What other evidence may help clarify previous performance?

Potentially relevant information may include:

- Previous calibration results
- Intermediate verification or check results
- Calibration and repair history
- Measurements from another instrument
- Redundant or confirming measurements
- Retest or reinspection data
- Product or process monitoring
- Known damage, overload, environmental exposure or other instrument events

What additional technical information may be useful?

Consider whether additional information is available from the calibration provider, including:

- Complete as-found and as-left data
- Measurement uncertainty
- Applicable decision rule
- Confirmation of the OOT result
- Technician observations
- Adjustment or repair information
- Historical calibration or repair records
- Technical consultation

Disclaimer

This guide is provided as a technical information and planning aid. It is not intended to prescribe an OOT investigation, product-impact assessment or quality-system procedure. Not every consideration will apply to every OOT result, and the questions do not represent mandatory steps or a required sequence. An OOT calibration result does not, by itself, establish that the instrument was unfit for its intended application or that previous measurements were adversely affected. Similarly, a successful adjustment or acceptable as-left calibration does not, by itself, establish that previous measurements were unaffected. Organizations should determine the appropriate evaluation and response through qualified personnel, approved procedures and applicable regulatory, contractual, customer and internal requirements.

OOT Information and Evidence Worksheet

Use this worksheet to organize technical information that may be relevant when an instrument is found out of tolerance.

1. Calibration data

Instrument: _____

Asset ID: _____

Calibration date: _____

Affected function: _____

Affected range: _____

Affected test point(s): _____

Calibration requirement/specification: _____

As-found result: _____

Applicable tolerance/acceptance limit: _____

Magnitude of observed deviation: _____

Direction of observed deviation: _____

Measurement uncertainty, when applicable: _____

Decision rule, when applicable: _____

Was the result repeated or confirmed? _____

Adjustment or repair performed: _____

Other relevant calibration observations: _____

_____

_____

_____

_____

2. Instrument-use information

Was the affected capability used during the period under consideration?

- ☐ Yes
- ☐ No
- ☐ Unknown

Functions/ranges used: _____

Relevant period of use: _____

Where was the instrument used? _____

What work or measurements did it support? _____

How were the measurements used? _____

- ☐ Informational only
- ☐ Process adjustment or troubleshooting
- ☐ Acceptance or rejection decision
- ☐ Test or inspection decision
- ☐ Maintenance or service decision
- ☐ Other: _____

If multiple previous measurements may be relevant, identify or attach the applicable measurement records, results and associated decisions:

_____

_____

Were measurements made at or near the affected test point?

- ☐ Yes
- ☐ No
- ☐ Unknown

Available usage records:

- ☐ Instrument-use records
- ☐ Work orders
- ☐ Production/test records
- ☐ Maintenance/service records
- ☐ Batch, lot or serial-number records
- ☐ Instrument-location history
- ☐ Software/audit-trail records
- ☐ Operator/technician records
- ☐ Other: _____

3. Application requirements

Applicable measurement requirement: _____

Product/process/service tolerance or acceptance criteria:

Were relevant previous results near an acceptance limit?

- ☐ Yes
- ☐ No
- ☐ Unknown

Relevant configuration, environmental conditions, fixtures, probes, cables or software:

Other application information that may provide context: _____

_____

4. Historical information

- ☐ Available information may include:
- ☐ Previous as-found calibration results
- ☐ Previous OOT results
- ☐ Intermediate verification/ check results
- ☐ Adjustment history
- ☐ Repair history
- ☐ Known damage or overload
- ☐ Transportation or storage incidents
- ☐ Unusual environmental exposure
- ☐ Changes in instrument behavior
- ☐ Other: _____

Relevant observations from historical information: _____

_____

5. Independent or confirming evidence

- ☐ Available evidence may include:
- ☐ Measurement from a second instrument
- ☐ Redundant measurement
- ☐ In-process check
- ☐ Reference standard result
- ☐ Product/process monitoring
- ☐ Retest data
- ☐ Environmental monitoring
- ☐ System-generated record
- ☐ Other: _____

What does the available evidence show?

_____

6. Open questions and limitations

Information that is unavailable or incomplete: _____

_____

Questions for the calibration provider: _____

_____

Questions referred to qualified internal functions: _____

_____

Other technical considerations or limitations: _____

_____

Important: This worksheet is provided as a technical information and planning aid. Not every section or field applies to every OOT result, and completing the worksheet does not constitute a required OOT investigation or quality-system procedure. An OOT calibration result does not, by itself, establish that an instrument was unfit for its intended application or that previous measurements were adversely affected. Organizations should determine the appropriate evaluation and response through qualified personnel, approved procedures and applicable requirements.

SIMCO

SIMCO is the leading provider of calibration and software services for technology organizations, bringing over 60 years of calibration industry leadership. Our experience enables us to develop exceptional solutions for service management.

Founded in 1962 to service NASA and high technology firms in Silicon Valley, SIMCO is committed to delivering life-saving quality leaner, by providing the highest level of quality and customer service.

Learn more at **www.simco.com**
or contact Sales at 866-299-6029

Headquarters:
3131 Jay St, Suite 100
Santa Clara, CA 95054